IECEx Quality Assessment Report: GB/SIR/QAR06.0018/06 details

QAR :	
QAR Reference Number *: (automatic numbering)	GB/SIR/QAR06.0018/06
Related QARs:	GB/SIR/QAR06.0018/00 GB/SIR/QAR06.0018/03 GB/SIR/QAR06.0018/02 GB/SIR/QAR06.0018/01 GB/SIR/QAR06.0018/04 GB/SIR/QAR06.0018/05
Status*:	Issued
QAR Free Reference Number*:	70017823
Audit Date*: (yyyy-mm-dd)	2015-02-04
Date of Issue*: (yyyy-mm-dd)	2015-03-11
Details of change*:	Recertification Audit
Valid until*: (yyyy-mm-dd)	2018-03-03
Site(s) audited*:	Peppers Cable Glands Limited Stanhope Road Camberley Surrey GU15 3BT
Issuing ExCB*:	SIR - SIRA Certification Service
Manufacturer*:	Peppers Cable Glands Limited Stanhope Road Camberley Surrey GU15 3BT
Country of Manufacture*:	United Kingdom
Product information*:	Cable glands, stopping plugs , seals and associated cable accessories
Protection concept*:	Flameproof, Increased Safety, Dust Ingress Protection, Restricted Breathing
Related IECEx Certificates: (automatic linking)	-
Related Certificates: (manual insertion)	IECEx SIR 05.0020X Cable Glands & Stopper Boxes
Related IECEx Certificates for all previous versions:	IECEx SIR 07.0098X issue: 3 [Current] IECEx SIR 07.0098X issue: 0 [Current] IECEx SIR 07.0099X issue: 0 [Current] IECEx SIR 07.0098X issue: 1 [Current] IECEx SIR 07.0096X issue: 0 [Current] IECEx SIR 07.0097X issue: 0 [Current] IECEx SIR 07.0098X issue: 5 [Current] IECEx SIR 07.0099X issue: 1 [Current] IECEx SIR 07.0096X issue: 1 [Current] IECEx SIR 07.0099X issue: 2 [Current] IECEx SIR 07.0097X issue: 1 [Current] IECEx SIR 07.0098X issue: 2 [Current] IECEx SIR 07.0098X issue: 4 [Current] IECEx SIR 07.0098X issue: 3 [Current] IECEx SIR 07.0098X issue: 1 [Current] IECEx SIR 09.0131X issue: 0 [Current] IECEx SIR 09.0132U issue: 0 [Current] IECEx SIR 09.0131X issue: 3 [Current] IECEx SIR 07.0098X issue: 5 [Current] IECEx SIR 07.0099X issue: 1 [Current] IECEx SIR 09.0131X issue: 2 [Current] IECEx SIR 07.0096X issue: 1 [Current] IECEx SIR 07.0099X issue: 2 [Current] IECEx SIR 07.0097X issue: 1 [Current]

IECEx SIR 07.0098X issue: 2 [Current]
IECEx SIR 07.0098X issue: 4 [Current]
IECEx SIR 09.0131X issue: 1 [Current]
IECEx SIR 09.0131X issue: 4 [Current]
IECEx SIR 09.0131X issue: 3 [Current]
IECEx SIR 07.0099X issue: 1 [Current]
IECEx SIR 09.0131X issue: 2 [Current]
IECEx SIR 07.0096X issue: 1 [Current]
IECEx SIR 07.0099X issue: 2 [Current]
IECEx SIR 07.0097X issue: 1 [Current]
IECEx SIR 09.0131X issue: 4 [Current]
IECEx SIR 07.0098X issue: 3 [Current]
IECEx SIR 09.0033X issue: 0 [Current]
IECEx SIR 10.0068U issue: 0 [Current]
IECEx SIR 09.0131X issue: 3 [Current]
IECEx SIR 07.0098X issue: 5 [Current]
IECEx SIR 07.0099X issue: 1 [Current]
IECEx SIR 09.0131X issue: 2 [Current]
IECEx SIR 07.0096X issue: 1 [Current]
IECEx SIR 07.0099X issue: 2 [Current]
IECEx SIR 07.0097X issue: 1 [Current]
IECEx SIR 07.0098X issue: 4 [Current]
IECEx SIR 09.0131X issue: 4 [Current]
IECEx SIR 07.0098X issue: 5 [Current]
IECEx SIR 07.0096X issue: 1 [Current]
IECEx SIR 07.0099X issue: 2 [Current]
IECEx SIR 07.0097X issue: 1 [Current]
IECEx SIR 09.0131X issue: 4 [Current]
IECEx SIR 09.0131X issue: 4 [Current]

Comment:

Attachment: